

## URGENT MEDICAL DEVICE CORRECTION

To users of the ACUSON Juniper and ACUSON Maple Ultrasound systems:

Dear Valued Customer:

This letter is to notify users of a potential safety concern specific to and limited to volume flow measurements in your Siemens Healthineers ACUSON Juniper and ACUSON Maple Ultrasound systems.

### **What is the issue?**

The system incorrectly performs a unit conversion of liters to milliliters using a multiplier of 100 (one hundred) instead of using the correct multiplier of 1000 (one thousand) in specific situations, described below. The result of this conversion error is the presentation of a 10x under-estimated measured value.

This unit conversion issue displays an inaccurate value that is 10x smaller than the actual measurement ONLY after a system is changed from the factory default configuration units of measure to display the following:

- Milliliters per second: unit displayed as either ml/sec or mL/sec

### **What is NOT affected by this issue?**

This issue does NOT affect volume flow measurements configured to display in liters.

- Liters per minute: unit displayed as either l/min or L/min – this is the default factory display configuration
- Liters per second: unit displayed as either l/sec or L/sec

This issue does NOT affect the Doppler ultrasound imagery displayed on the Ultrasound system.

### **What is the potential risk to patient safety?**

If undetected and used in isolation, volume flow measurement values that are under-represented by a factor of 10 could contribute to misdiagnosis of a patient's condition or influence patient management decisions in a negative way.

The potential risk of misdiagnosing a severe condition from an under-represented volume flow measurement is unlikely as a volume flow measurement is only one of several independently measured parameters. Also, the Doppler imaging and other adjunctive diagnostics would conflict with an erroneous volume flow measurement.

As of August 2024, Siemens Healthineers has not received any report of injuries related to this issue.

### **What steps can the user take to avoid the potential risk of this issue?**

To avoid potential misdiagnosis by an under-represented volume flow measurement value, use the factory default display configuration of l/min (liters per minute).

### **What if I used the inaccurately converted volume flow units of measurement within a clinical context?**

Siemens Healthineers recommends a review of previous examination results ONLY if a clinical assessment reviewed a volume flow measurement(s) with the unit of measurement configured to display a value in milliliters.

Should an adverse event or quality problem be experienced with the use of this product, please report the incident to Siemens Healthineers.

**How will the issue be resolved?**

Siemens Healthineers will correct this issue with a free-of-charge software update to your ACUSON Juniper and ACUSON Maple systems.

Your Customer Service Engineer from Siemens Healthineers will contact you to schedule a facility visit to update the system or inform you of a remote update when the software update is available. The software update is currently under development and estimated to be available in the summer of 2024.

**Dissemination of the content of this notice:**

Please ensure that all users of ACUSON Juniper and ACUSON Maple systems within your organization, and others who may need to be informed, receive the safety relevant information provided with this notice and take the actions specified herein.

If an adverse event or quality problem is experienced with the use of this product, the issue may be reported to the FDA's MedWatch Adverse Event Reporting program either online, or by regular mail or fax.

Patient safety and customer satisfaction are our highest priorities. We appreciate your cooperation with this product advisory and apologize for any inconvenience this causes your institution. If you have further questions, please contact the Siemens Healthineers Ultrasound Service Customer Care Center at 1-800-888-7436.

Sincerely,



*Electronically signed by: James Dabbs  
Reason: I am approving this document  
Date: Aug 7, 2024 11:26 PDT*

James R. Dabbs  
Vice President, Quality & Regulatory  
Siemens Medical Solutions USA, Inc.  
Ultrasound Business Area

**Affected software versions:**

<b>Ultrasound System</b>	<b>REF / Model</b>	<b>Software Versions</b>
ACUSON Juniper 1.0	11335791	VA10G and prior
ACUSON Juniper 1.5		VB10H and prior
ACUSON Juniper 2.0		VB11C and prior
ACUSON Juniper 2.5		VB30D and prior
ACUSON Juniper Select 2.0	11653093	VB11C and prior
ACUSON Juniper Select 2.5		VB30D and prior
ACUSON Maple 1.0	11711750	VA10A
ACUSON Maple Select 1.0	11711779	VA10A

11659961-691-001-02

2/66