

New Field Safety Notice
Urgent Medical Device Correction - Grip Cable Failures
on da Vinci X and Xi Reusable Instruments with Jaws (ISIFA2024-09-C)

1- Introduction
and Reason for
Field Action

Dear Intuitive Customer,

This Field Safety Notice is to notify you that Intuitive has become aware of an **increase in complaints** regarding frayed or broken cables on some da Vinci X and Xi reusable instruments. We refer to these frayed or broken cables as “failures”. There are two grip cables in the instruments which control the opening and closing of the jaws of the instrument (as shown in Figure A). The grip cable is the same across all da Vinci X and Xi reusable instruments with jaws.




Figure A: 10x magnification of an example of an intact grip cable of a da Vinci Xi instrument.




Figure B: 10x magnification of an example of an intact grip cable of a Bipolar da Vinci Xi instrument.

A grip cable can fail partially (i.e., frayed) or completely (i.e., broken). A broken grip cable can lead to loss of grip functionality, exposure to frayed cables, or the potential for tungsten cable particulate to fall into the patient. If a cable were to fail, it would be retained within the shaft of the instrument. As a result, fragments would not fall into the patient, though particulate may be generated. A partial failure might not affect grip functionality but may lead to exposure to frayed cables.

Figures C and D below show examples of broken and frayed grip cables.



Figure C: 20x magnification of a broken grip cable on a da Vinci Xi instrument.



Figure D: 20x magnification of a frayed grip cable a da Vinci Xi instrument

Intuitive completed an investigation that reviewed grip cable failure complaints and did not identify any new or increased severity of harm. Therefore, you may continue to use these instruments in accordance with the user manual.

2 - Risk to Health

Complete or partial failure of a grip cable can lead to loss of grip functionality, exposure to frayed cables, and/or tungsten cable particulate.

Loss of grip functionality:

Complete failure of a grip cable would be immediately detected in most cases due to the loss of grip functionality. The loss of grip functionality could result in a **minor procedure delay (< 30 minutes)** to replace an instrument, re-establish retraction of grasped tissue, or retrieve a dropped suture needle. It is possible that complete loss of grip functionality could result in **tissue injury or bleeding** if grasped tissue falls out of the grips and interacts with another instrument, or if unexpected grip positioning causes unintended interaction with tissue.

For bipolar energy instruments, complete failure of grip cable may cause an inability to sufficiently close the jaws for bipolar energy delivery. If bleeding is occurring at this time, it may require **alternate means of intervention to regain hemostasis**.

Exposure to frayed cables:

If a frayed cable occurs, there can be unintended interaction between tissue and the cable. This interaction could result in **tissue injury** requiring intervention like physical pressure, cauterization, or suturing.

Cable Particulates:

Cable breakage or fraying will not result in fragmentation of the entire cable, (e.g., separation of significant portion of cable) as it is retained on both ends within the shaft of

	<p>the instrument. It is possible that tungsten cable particulate could fall into the patient if cable failure occurs. Retrieval of fallen particulate by the user may incur a minor procedure delay (< 30 minutes). Tungsten has a safe biocompatibility profile and is MRI-compatible, so any retained cable material is unlikely to cause adverse biological reaction.</p> <p>From October 1, 2022, through August 31, 2024, a total of 13 adverse events have been reported due to grip cable failures in the European Region.</p>
<p>3- Affected Products</p>	<p>All da Vinci X and Xi reusable instruments with jaws are affected by this communication.</p> <p>The grip cable failure rate for the period of October 2022 through August 2024 across all da Vinci X and Xi reusable instruments with jaws is 0.82% worldwide. This rate is calculated by dividing number of complaints received for grip cable failure by total number of procedures performed using the affected reusable instruments with jaws.</p> <p>Refer to Appendix A for a list of affected Part Numbers. Appendix A also includes information on instrument part numbers that contributed to the increasing failure rate.</p>
<p>4- Actions to be taken by the Customer/User</p>	<ol style="list-style-type: none"> 1. Customers can continue using the products in accordance with the user manual. 2. As a reminder, when using da Vinci X and Xi reusable instruments, follow the Inspection Before Use and Warnings listed in the manual provided with your system to inspect for any broken cables. Refer to Figures C and D for examples. In addition, please refer to Appendix B for additional images for detection of grip cable failures. 3. If you observe any failed grip cables, please inform Intuitive via the standard complaint process and return the RMA process. <p><u>Please take the following standard actions related to Field Safety Notifications:</u></p> <ul style="list-style-type: none"> • Complete the attached Acknowledgement Form immediately and return it via email to Intuitive as instructed on the form. • Ensure that the content of this notification is passed on to all those who need to be aware within your organization or functions where the affected instruments have been transferred. • Retain a copy of this notification, place a copy with your affected system, ensuring it is placed likely to be seen/viewed by the operators, and keep the acknowledgement form for your files. • Inform Intuitive of any Serious Incidents* or quality problems concerning the use of the subject instruments via the standard complaint process. • Additionally, if Serious Incidents* or quality problems are experienced, please follow your standard reporting process to your health authority, as applicable.

<p>5- Actions to be taken by Intuitive</p>	<p>Intuitive takes customer complaints very seriously and completed a detailed investigation on grip cable failures. This investigation concluded that the da Vinci X and Xi reusable instruments remain safe to use.</p> <p>Intuitive is committed to patient safety and has already started implementing updated products with an intent to reduce cable failures on da Vinci X and Xi reusable instruments.</p> <p>Any instruments returned to Intuitive for failed cable(s) and confirmed per the RMA process, will be provided credit for remaining uses.</p>
<p>6- Further Information & Support</p>	<p>If you need further information or support concerning this Field Safety Notice, please contact your Clinical Sales Representative or contact Intuitive Customer Service at the numbers listed below:</p> <ul style="list-style-type: none"> • Europe, Middle East, Asia and Africa: +800 0821 2020 or +41 21 821 2020 (8 am to 6 pm CET) or euucs@intusurg.com

Please be informed that the appropriate Regulatory Authority for your region has been notified of this Field Safety Corrective Action

Sincerely,

Intuitive Surgical SAS
 11 avenue de Canteranne
 Pessac FRANCE

Definition:

*Serious Incident (EUMDR 2017/745) is defined as “any incident that directly or indirectly led, might have led or might lead to any of the following:

- a. the death of a patient, user or other person
- b. the temporary or permanent serious deterioration of a patient’s, user’s, or other person’s state of health,
- c. a serious public health threat

ACKNOWLEDGEMENT FORM

New Field Safety Notice

Urgent Medical Device Correction - Grip Cable Failures on da Vinci X and Xi Reusable Instruments with Jaws (ISIFA2024-09-C)

Ship-to:

Hospital Name: _____

Address: _____

City, State, Zip: _____

SFID: _____

ATTENTION: _____

PLEASE COMPLETE ALL REQUESTED INFORMATION AND RETURN IMMEDIATELY

- 1. I have received and read this notice.
- 2. I have ensured all appropriate personnel are fully informed of the contents of this notice.
- 3. I will contact Intuitive if I have any questions.

Hospital name: _____

Name (print): _____

Signature: _____

Phone Number: _____

Email: _____

Date: _____

Position:

- Robotics Coordinator
- Operating Room Director
- Risk Manager
- Surgeon
- Other: _____

**PLEASE EMAIL THIS ACKNOWLEDGEMENT FORM TO Intuitive
ATTN: REGULATORY COMPLIANCE FIELD ACTIONS
Subject line for email: ISIFA2024-09-C
Scan and Email to: EU.FSCA@intusurg.com**

Customer Service:

- Europe, Middle East, Asia and Africa: +800 0821 2020 or +41 21 821 2020 (8 am to 6 pm CET)

Appendix A: Affected product and updated product information

Note: Product numbers in **bold** in Table A1 have shown increase in grip cable failure complaints.

Table A1: Affected Product Information

Affected Product	Product Name	UDI Number
470179	Monopolar Curved Scissors (Hot Shears)	00886874112298
470205	Fenestrated Bipolar Forceps	00886874112359
471205	Fenestrated Bipolar Forceps (Extended Use Program)	00886874119808
471093	Prograsp Forceps (Extended Use Program)	00886874119785
470049	Cadiere Forceps	00886874112250
471049	Cadiere Forceps (Extended Use Program)	00886874119778
470172	Maryland Bipolar Forceps	00886874112281
471172	Maryland Bipolar Forceps (Extended Use Program)	00886874119792
470405	Force Bipolar	00886874115930
471405	Force Bipolar (Extended Use Program)	00886874120767
470400	Long Bipolar Grasper	00886874113530
471400	Long Bipolar Grasper (Extended Use Program)	00886874121528
470006	Large Needle Driver	00886874112151
471309	Mega SutureCut Needle Driver (Extended Use Program)	00886874119815
470296	Large SutureCut Needle Driver	00886874112410
471296	Large SutureCut Needle Driver (Extended Use Program)	00886874121504
470093	Prograsp Forceps	00886874112267
470309	Mega SutureCut Needle Driver	00886874112434
471006	Large Needle Driver (Extended Use Program)	00886874119754
470194	Mega Needle Driver	00886874112342
470347	Tip-Up Fenestrated Grasper	00886874112496
470401	Small Clip Applier	00886874112670
470327	Medium-Large Clip Applier	00886874112465
470230	Large Clip Applier	00886874112380
470207	Tenaculum Forceps	00886874112366
470048	Long Tip Forceps	00886874112243
471048	Long Tip Forceps (Extended Use Program)	00886874121467
470036	DeBakey Forceps	00886874112236
470181	Resano Forceps	00886874112304
470171	Micro Bipolar Forceps	00886874112274

Affected Product	Product Name	UDI Number
471171	Micro Bipolar Forceps (Extended Use Program)	00886874121474
470033	Black Diamond Micro Forceps	00886874112229
470318	Small Graptor (grasping retractor)	00886874112441
470344	Curved Bipolar Dissector	00886874112489
471344	Curved Bipolar Dissector (Extended Use Program)	00886874121511
470001	Potts Scissors	00886874112120
470007	Round Tip Scissors	00886874112168
470190	Cobra Grasper	00886874112335
471190	Cobra Grasper (Extended Use Program)	00886874121481
470246	Atrial Retractor Short Right	00886874112397
470249	Dual Blade Retractor	00886874112403

Intuitive is implementing a design update to reduce cable failures on da Vinci X/Xi reusable instruments with jaws. Our ability to implement product updates across our entire portfolio is currently constrained due to manufacturing capacity and regulatory approvals. We have begun shipping updated product on *some* instruments (identified in Table A2) and are actively working on getting the updates implemented on the remainder of the products (identified in Table A3).

As noted above, availability of updated product may vary depending on region. Please contact your local Clinical Sales Representative or Customer Service to understand availability and timing for when updated product will become available for your region(s).

Table A2: Updated Product Information – Below table provides information on part numbers where updated product have been implemented. Refer to ‘Updated Product Version’ column for information on **the version of product** that has the update.

Note: All future versions will also include the updated product.

Affected Product	Updated Product Version	Product Name
470179	21	Monopolar Curved Scissors (Hot Shears)
470205	19	Fenestrated Bipolar Forceps
471205	19	Fenestrated Bipolar Forceps (Extended Use Program)
471093	14	Prograsp Forceps (Extended Use Program)
470172	19	Maryland Bipolar Forceps
471172	19	Maryland Bipolar Forceps (Extended Use Program)
470400	12	Long Bipolar Grasper
471400	12	Long Bipolar Grasper (Extended Use Program)
470006	14	Large Needle Driver
471309	Version* 16: Starting from Lot# K11231218	Mega SutureCut Needle Driver (Extended Use Program)
470296	10	Large SutureCut Needle Driver

Affected Product	Updated Product Version	Product Name
471296	Version 8*: Starting from K10231218	Large SutureCut Needle Driver (Extended Use Program)
470093	14	Prograsp Forceps
470309	18	Mega SutureCut Needle Driver
471006	13	Large Needle Driver (Extended Use Program)
470194	9	Mega Needle Driver
470401	12	Small Clip Applier
470327	15	Medium-Large Clip Applier
470230	15	Large Clip Applier
470207	13	Tenaculum Forceps
470036	7	DeBakey Forceps
470181	11	Resano Forceps
470318	15	Small Graptor (grasping retractor)
470344	19	Curved Bipolar Dissector
471344	19	Curved Bipolar Dissector (Extended Use Program)
470001	12	Potts Scissors
470007	8	Round Tip Scissors

* For PN471309 & PN471296 the updates to reduce grip cable failures were implemented on a prior version which can be identified via the lot number mentioned in Table A2. The last 6 numbers of the lot number imply the manufacturing date of the instruments. The date format is modeled based on “YYMMDD”. Refer to Figure E for an example. Any lots built beyond the date for the affected product identified in Table A2 contain the updated product.




Figure E: An example of lot that was manufactured on 29th June 2017

Please see photos below of where the version number is located on the instrument box (Figure F) as well as the instrument casing (Figure G).

EndoWrist® Instruments
Monopolar Curved Scissors



Part Number → **REF** 470179

Lot Number → **LOT** S10170629

QTY 1

VER 23 ← Version Number

USES 10

da Vinci Si
 da Vinci Xi
 da Vinci Xi

Figure F: Location of Part Number and Version on Instrument Box

Rear Face




Figure G: Location of Part, Lot and Version Number on Instrument Casing

Table A3: Part Numbers Pending Implementation of Updated Product – Below table provides information on part numbers where Intuitive is still in process getting the updated product implemented. However, we have included ‘Updated Product Version’ column to help identify unaffected product versions when they become available.

Note: All future versions will also include the updated product.

Affected Product	Updated Product Version	Product Name
470049	11	Cadiere Forceps
471049	11	Cadiere Forceps (Extended Use Program)
470405	9	Force Bipolar
471405	9	Force Bipolar (Extended Use Program)
470347	17	Tip-Up Fenestrated Grasper
470048	11	Long Tip Forceps
471048	12	Long Tip Forceps (Extended Use Program)
470171	17	Micro Bipolar Forceps
471171	17	Micro Bipolar Forceps (Extended Use Program)
470033	12	Black Diamond Micro Forceps
470190	6	Cobra Grasper
471190	6	Cobra Grasper (Extended Use Program)
470246	11	Atrial Retractor Short Right
470249	12	Dual Blade Retractor

Appendix B: Additional Images for Detection of Grip Cable Failures

In addition to instructions provided in da Vinci Xi and da Vinci X Instruments and Accessories User Manual, the following section provides additional images and detailed steps on how to inspect for broken or frayed grip cable which may be detected visually prior to or during use.

The inspection is limited to the instrument wrist and does not require magnification as shown in the pictures within this letter. Articulation of the instrument wrist is not required but inspection of cables on both sides of the wrist is required.

1. Inspection Prior to Use

Prior to use, visually inspect all instruments for broken or frayed cable per Figures H & I below




Figure H: Broken Cable



Figure I: Frayed Cable

2. Detection during use

A. Broken Cable

- If an instrument with a broken grip cable is installed on the system, it could result in engagement failure which will prevent completion of installation and will be immediately detected by the surgeon.
- If a grip cable breaks intraoperatively on an installed instrument, the failure would be immediately detected by the surgeon as they would lose grip function (i.e. loss of grasp on any object within the instrument jaws).

B. Frayed Cable

- Frayed grip cables may be identified through endoscopic view. Existing frayed grip cable failure will not result in affected grip motion as the grip cable will remain connected.
- Frayed cables that are not visually identified would be unlikely to cause any unintended tissue interactions.