

«Hospital\_Name»

«Users\_Name»

«Department»

«Customer\_Address»

«Zip\_Code» «City»

«Country\_Name»

<Reference: 97125289E-FA>

20 August 2025

## Urgent Field Safety Notice

**Subject: Field Safety Notice** – Software to enhance Safety Architecture is available and designed to prevent initiation of Safety Mode in an ambulatory setting due to a high battery impedance state for the ACCOLADE™ family of devices which includes ACCOLADE, PROPONENT™, ESSENTIO™, and ALTRUA™ 2 dual chamber (DR) standard life (SL) and DR extended life (EL) pacemakers; and VISIONIST™ and VALITUDE™ cardiac resynchronization therapy pacemakers (CRT-Ps). (Boston Scientific Field Action Reference: 97125289E-FA).

Dear Physician or Healthcare Professional (HCP),

This notice provides an update to the December 2024 customer communication regarding the potential for the ACCOLADE family of pacemakers to initiate Safety Mode due to a high battery impedance state.

- A software upgrade (Model 3869 v2.04) is now available (CE Marked) for the LATITUDE™ Programming System, Model 3300 (programmer), which upon interrogation of a pacemaker from the ACCOLADE family enables detection of an elevated battery impedance by a Code-1003 alert and, after three (3) or more months of increasing battery impedance, disables wandless ZIP™ telemetry (i.e., radio frequency) before initiation of Safety Mode.
- By design, disablement of ZIP telemetry eliminates the potential for Safety Mode in an ambulatory setting for any device upgraded with this software that is experiencing a high battery impedance state.
- With the availability of this software, **prophylactic replacement is no longer recommended for patients at risk of harm due to the non-programmable parameters in Safety Mode**, see updated recommendations below in Table 1.
- All ACCOLADE pacemakers will benefit from this software upgrade. Boston Scientific is expanding our recommendations to all device types in the Accolade family. For precise details about the bounding of affected devices, see Appendix A.

## Recommendations

These recommendations are intended to promote a risk-stratified, timely upgrade of pacemaker software to prevent the occurrence of Safety Mode in an ambulatory setting due to a high battery impedance state.

- Connect your LATITUDE programmer to the internet (e.g., via WiFi, ethernet, or cell adapter), select Utilities>Software Update>Easy Install, and wait for the programmer to install Model 3869 v2.04 software. Maintain internet connection and power until the installation is complete.
- If your programmer cannot be connected to the internet, contact your local Boston Scientific sales professional to arrange for your programmer's software to be upgraded.

**Table 1** Recommendations for ACCOLADE pacemakers with availability of Model 3869 v2.04 software

|                                                                                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                                              |                                                                |
|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------------------------|
| Upgrade pacemaker or CRT-P software                                               | For patients at risk of harm due to Safety Mode: If longevity remaining is four (4) years or less OR will reach four (4) years or less before the next scheduled follow-up, promptly schedule an in-person follow-up.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |                                              | For all other patients: Schedule the next follow-up in-person. |
|                                                                                   | During the in-person follow-up, interrogate the device using a Model 3300 LATITUDE programmer installed with Model 3869 v2.04 software.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |                                              |                                                                |
| Follow-up Interval                                                                | After device software has been upgraded by Model 3869 v2.04 software on a Model 3300 LATITUDE programmer, perform system follow-up in accordance with instructions for use (IFU).                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |                                              |                                                                |
| Replace if high battery impedance state is detected                               | If either an alert for voltage too low for remaining longevity (Code-1003) or wandless ZIP telemetry disablement warning message is observed, contact technical services for a customized recommended replacement interval.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |                                              |                                                                |
| LATITUDE not monitored list                                                       | If a device upgraded with this software detects a high battery impedance state (e.g., Code-1003), remains in service, and the battery impedance continues rising, the device with this software, by design, will disable wandless ZIP telemetry to prevent Safety Mode initiation. <ul style="list-style-type: none"><li>• If wandless ZIP telemetry is disabled, the patient may be listed as not monitored in the LATITUDE Remote Patient Management System (RM) website after 14 days or more.</li><li>• If all other causes for the patient not being monitored are ruled out (e.g., communicator connection/power is confirmed), schedule an in-person follow-up to assess wandless ZIP telemetry performance.</li></ul> |                                              |                                                                |
| Replace the device if it enters Safety Mode before receiving the software upgrade | For patients at risk of harm: Emergent/Urgent Replacement <ul style="list-style-type: none"><li>• When choosing a replacement interval, do not rely on previously reported battery time remaining estimates which do not account for Safety Mode’s increased outputs nor the battery’s high impedance state.</li><li>• During replacement of a device in Safety Mode, pacing inhibition should be anticipated during electrocautery and when the device is removed from the pocket due to unipolar pacing and high sensitivity.</li></ul>                                                                                                                                                                                     | All other patients: Non-emergent Replacement |                                                                |
| Prophylactic Replacement                                                          | Not recommended for patients who have been interrogated with a Model 3300 LATITUDE programmer with Model 3869 v2.04 installed.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                              |                                                                |
| Medical Records                                                                   | For each patient with an affected device, append/update the patient’s medical record with this letter to maintain awareness to all follow-up physicians of this topic for the remaining service life of the device.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                              |                                                                |

## Clinical Impact

Safety Mode provides back-up pacing under critical circumstances; it is not intended to be a substitute for chronic pacing therapy. The non-programmable Safety Mode pacing parameters (Table 3) may not provide optimal support of a patient's cardiac condition (e.g., adequacy of underlying escape rhythm, the need for AV/VV pacing for cardiac synchrony, and/or the potential for pacing inhibition due to myopotential oversensing). Pacing inhibition due to myopotential oversensing for unipolar sensing configurations is well documented, however, provocative maneuvers, including isometric exercises, are not a reliable predictor of myopotential oversensing susceptibility for patients who may transition to Safety Mode.

The most common clinical outcome of this behavior is early device replacement. In certain patients, Safety Mode may result in unintended clinical impact such as pacing inhibition/pauses, muscle stimulation (e.g., skeletal muscle or phrenic nerve stimulation), or heart failure decompensation prior to device replacement. Among patients at risk of harm whose pacemaker initiates Safety Mode, Caughron et al. reported 52% rate of major complications due to presyncope, syncope, fall with trauma, pauses/asystole, and death.<sup>1</sup> Remote monitoring is a standard of care<sup>2</sup>, is a critical device management capability, and is an important means to detect onset of high battery impedance with this software upgrade.

The worst case reported patient harm has been loss of pacing with serious injury or life-threatening outcome. There have been two (2) deaths in pacemaker dependent patients after initiating Safety Mode in an ambulatory setting and no additional deaths have been reported since that time. Details about the ACCOLADE subpopulations and projected lifetime occurrence rate for each device type are reported in Table 2. Occurrence rates for various device types are reported in Figure 1 and 2.


**Table 2** ACCOLADE populations and occurrence rates for Safety Mode (SM) due to high battery impedance

| Population                           | Device Type | Estimated WW Active Population | Estimated WW Distributed Population | SM Events | Lifetime Occurrence Rate |
|--------------------------------------|-------------|--------------------------------|-------------------------------------|-----------|--------------------------|
| <b>Dec 2024 Advisory Populations</b> | CRT-P       | 8,500                          | 21,300                              | 281       | 3.27% at 117 months      |
|                                      | DR EL       | 34,300                         | 58,600                              | 183       | 3.27% at 158 months*     |
|                                      | DR SL       | 56,500                         | 123,400                             | 605       | 0.75% at 102 months      |
| <b>All other devices</b>             | CRT-P       | 92,500                         | 124,100                             | 83        | 1.16% at 117 months      |
|                                      | DR EL       | 444,300                        | 534,200                             | 23        | 1.16% at 158 months*     |
|                                      | DR SL       | 539,700                        | 683,000                             | 125       | 0.14% at 102 months      |
|                                      | SR SL       | 189,500                        | 294,900                             | 60        | 0.19% at 117 months      |
| <b>Total</b>                         |             | 1,365,300                      | 1,839,400                           | 1,360     |                          |


\*DR-EL rate is projected based on the experience of CRT-P which uses the same EL battery

<sup>1</sup>Caughron H, Dhruva SS, Raitt MH. Complications Associated With Safety Mode Initiation in Recalled Boston Scientific Pacemakers. J Am Coll Cardiol. 2025 Apr 5:S0735-1097(25)05926-1. doi: 10.1016/j.jacc.2025.03.501. Epub ahead of print. PMID: 40202463.

<sup>2</sup>In patients with CIEDs, RM is recommended as part of the standard of care (COR-1/LOE-A) pg e99. Ferrick AM Raj SR, Deneke T, et al. 2023 HRS/EHRA/APHRS/LAHR expert consensus statement on practical management of the remote device clinic. Heart Rhythm, ISSN: 1547-5271, Vol: 20, Issue: 9, Page: e92-e144. <https://doi.org/10.1016/j.hrthm.2023.03.1525>.



**Figure 1** Occurrence rates for high battery impedance induced Safety Mode in the December 2024 advisory population



**Figure 2** Occurrence rates for high battery impedance induced Safety Mode in remaining devices

### Description of Software Enhancement.

Wandless ZIP telemetry operations such as active telemetry sessions and automatic ZIP wakeups are the highest power operations performed in the ACCOLADE family of pacemakers and account for all confirmed instances of Safety Mode events. This software enhances Safety Architecture by adding a new daily wandless ZIP telemetry activated battery test<sup>1</sup> which assesses the battery's response to short bursts (e.g., milliseconds) of telemetry, detects/alerts onset of a high battery impedance state, and intervenes three (3) or more months later to prevent Safety Mode initiation. This is accomplished in two sequential stages.

1- If this telemetry activated battery test detects an elevated battery impedance state, the following alert: "Voltage too low for projected remaining longevity" (Code-1003) will be displayed via the LATITUDE programmer or LATITUDE RM. This first stage is designed to detect and alert users about a high battery impedance condition at least 3 months before pacemakers without this software would have initiated Safety Mode.

2- If a pacemaker from the ACCOLADE family with an elevated battery impedance induced Code-1003 remains in service, this telemetry activated battery test continues assessing the battery impedance (e.g., for three or more months) and disables wandless ZIP telemetry operation before the impedance achieves a level where Safety Mode has historically been initiated.

By design, this daily wandless ZIP telemetry activated battery test enhances the ACCOLADE family's Safety Architecture by eliminating the potential for Safety Mode initiation in an ambulatory setting due to a high battery impedance state. Please note the following:

- Code-1003 is a nonspecific alert condition that can be initiated for a high battery impedance state or detection of other anomalous system conditions. By contacting technical services when a Code-1003 is observed, an engineering analysis can determine a customized replacement interval.
- If wandless ZIP telemetry is disabled, the LATITUDE RM system will post the patient on the Not Monitored list in 14 or more days and an alert message will be displayed to the HCP upon interrogation by a LATITUDE programmer.
- Pacemaker longevity is not affected by a high battery impedance state when initiation of Safety Mode is prevented. In this circumstance, longevity is anticipated to be normal and battery status is extremely unlikely to initiate elective replacement before the labeled follow-up interval.
- After the device's software has been upgraded, the earliest a device experiencing a high battery impedance will initiate a Code-1003 alert is four (4) days later. Therefore, the software will not detect a high battery impedance state when device software is upgraded during an in-office programmer interrogation, rather the Code-1003 will be initiated four (4) or more days later.

<sup>1</sup>The daily wandless ZIP telemetry activated battery test is estimated to reduce device longevity by one (1) day for every 10 years of testing.

**Description of High Battery Impedance Behavior Without Software Upgrade**

As described in the original December 2024 advisory, ACCOLADE devices have a potential of exhibiting a high impedance condition because of unanticipated concentration of lithium salts resulting from variability of battery assembly techniques. This may result in a lack of available electrolyte between the battery anode and cathode.

High battery impedance may cause a device to exhibit transient voltage decreases during wandless ZIP telemetry operations. If the battery voltage drops below a minimum threshold during a high-power state (e.g., active ZIP telemetry), a system reset is automatically performed, and the conditions of the high-power state are interrupted. Subsequent high-power states may result in additional system resets due to the high battery impedance.

If three (3) system resets occur within a 48-hour period, the device is designed to enter Safety Mode to maintain backup pacing with pre-defined, non-programmable settings (Table 3). When a device is in Safety Mode, healthcare professionals (HCPs) are directed to contact Boston Scientific via a LATITUDE™ programmer warning screen and a LATITUDE remote patient management system red alert. Once a device enters Safety Mode, life-sustaining therapy continues to be available while battery capacity is available. The susceptibility of experiencing a high battery impedance and entering Safety Mode has been observed when the device reaches approximately four (4) years or less of remaining battery longevity.

**Table 3** Safety Mode Non-Programmable Settings

Per the IFU, Safety Mode is intended to provide life-sustaining therapy if repeated system resets occur with the following pre-defined, non-programmable parameters. A device that enters Safety Mode should be replaced.

| Parameter               | Setting                                |
|-------------------------|----------------------------------------|
| Mode                    | VVI, biventricular pacing for CRT-Ps   |
| Rate                    | 72.5 ppm                               |
| Sensitivity             | Automatic Gain Control (AGC) 0.25 mV   |
| Output                  | 5.0 V at 1.0 ms RV (and LV for CRT-Ps) |
| Lead Configuration      | RV/LV Unipolar sensing/pacing          |
| RVRP                    | 250 ms                                 |
| Noise response          | VOO                                    |
| LV Offset (CRT-Ps only) | 0 ms                                   |
| Magnet Response         | Disabled                               |

When replacing a device in Safety Mode, the following conditions may interrupt pacing during the procedure:

- During applications of electrocautery, pacing may be inhibited due to Safety Mode’s high sensitivity setting and unipolar sensing configuration.
- When removing the device from the pocket, loss of capture will occur due to Safety Mode’s unipolar pacing configuration.

During normal operations when a device is indicated for replacement, the system is designed to reserve sufficient battery capacity to support device operations for three (3) months to allow for a replacement procedure to be scheduled. However, if a device without upgraded software enters Safety Mode due to the high battery impedance, the reserve battery capacity may not be sufficient to support device operations for three months and should be scheduled for replacement soon thereafter and emergently for patients at risk of harm from Safety Mode parameters.

The ACCOLADE family of pacemakers includes a standard life (SL) battery for single chamber (SR) and dual chamber (DR) pacemakers and a larger, extended life (EL) battery for DR pacemakers and cardiac resynchronization therapy pacemakers (CRT-Ps). Because of disparate batteries (e.g., SL vs. EL) and therapies provided (e.g., SR/DR pacemakers vs. CRT-Ps), the occurrence rates vary (Figure 1 and 2). However, the susceptibility for a device to enter Safety Mode due to high battery impedance occurs when the device reaches approximately four (4) years or less of remaining battery longevity. A retrospective study of 121 US Department of Veterans Affairs (VA) Centers found that, of ACCOLADE and INGENIO devices initiating Safety Mode due to high battery impedance, 100% did so with 4 years or less time remaining and 92% with 2 years or less time remaining.<sup>1</sup>

<sup>1</sup>Caughron H., 2025 Apr 5:S0735-1097(25)05926-1. doi: 10.1016/j.jacc.2025.03.501.

The Regulatory Authority of your country has been informed about this customer communication. Adverse events should be reported to Boston Scientific and Regulatory Authorities if appropriate.

A patient letter is available upon request, which can be distributed to the patient.

Please **complete the enclosed Acknowledgment Form** and **send it to Boston Scientific at «Customer\_Service\_Fax\_Number» by 8 September 2025**. A completed form is required from every facility who receives this letter.

#### **Additional Information**

Patient safety remains Boston Scientific's highest priority, and we are committed to communicating up-to-date information with physicians and healthcare professionals to ensure you have timely, relevant information for managing your patients. Product performance information, including this topic, a device lookup tool, and resources for returning product are available within our Product Performance Resource Center at [www.bostonscientific.com/ppr](http://www.bostonscientific.com/ppr).

If you have additional questions regarding this information, please contact your Boston Scientific representative or Technical Services.

Sincerely,



Alexandra Naughton  
Vice President, Quality Assurance

Attachment: Acknowledgement Form

## Appendix A

Because of the latency associated with high battery impedance induced Safety Mode, the population has been expanded to include devices from the ACCOLADE family with a use-by-date (UBD) on or before 30 June 2025. All patients will benefit from this software update. This bounding is intended to prioritize pacemakers presently susceptible to Safety Mode due to a high battery impedance state with consideration for the additional in-clinic follow-up burden. Other pacemakers from the ACCOLADE family will not be susceptible for two years beyond this UBD and are therefore anticipated to receive this software through normal in-person follow-up scheduling. The expanded advisory population includes the following model numbers; however, these device attributes are not sufficient to precisely identify individual devices in the advisory population. Contact your local Boston Scientific sales professional for an affected serialized device list or enter a model/serial into the device lookup tool at [www.BostonScientific.com/lookup](http://www.BostonScientific.com/lookup).

| GTIN           | Model | Product Name       | GTIN           | Model | Product Name        | GTIN           | Model | Product Name           |
|----------------|-------|--------------------|----------------|-------|---------------------|----------------|-------|------------------------|
| 00802526558900 | L100  | ESSENTIO SR SL     | 00802526593246 | L201  | PROPONENT DR SL     | 00802526609015 | L310  | ACCOLADE MRI SR SL     |
| 00802526558917 | L100  | ESSENTIO SR SL     | 00802526611834 | L201  | PROPONENT DR SL     | 00802526611803 | L310  | ACCOLADE MRI SR SL     |
| 00802526571923 | L100  | ESSENTIO SR SL     | 00802526559068 | L209  | PROPONENT VDDR SL   | 00802526559228 | L311  | ACCOLADE MRI DR SL     |
| 00802526571930 | L100  | ESSENTIO SR SL     | 00802526572166 | L209  | PROPONENT VDDR SL   | 00802526559235 | L311  | ACCOLADE MRI DR SL     |
| 00802526571947 | L100  | ESSENTIO SR SL     | 00802526576386 | L209  | PROPONENT VDDR SL   | 00802526572395 | L311  | ACCOLADE MRI DR SL     |
| 00802526576300 | L100  | ESSENTIO SR SL     | 00802526576881 | L209  | PROPONENT VDDR SL   | 00802526572401 | L311  | ACCOLADE MRI DR SL     |
| 00802526576805 | L100  | ESSENTIO SR SL     | 00802526611889 | L209  | PROPONENT VDDR SL   | 00802526572418 | L311  | ACCOLADE MRI DR SL     |
| 00802526593109 | L100  | ESSENTIO SR SL     | 00802526559075 | L210  | PROPONENT MRI SR SL | 00802526576461 | L311  | ACCOLADE MRI DR SL     |
| 00802526611605 | L100  | ESSENTIO SR SL     | 00802526559082 | L210  | PROPONENT MRI SR SL | 00802526576966 | L311  | ACCOLADE MRI DR SL     |
| 00802526558924 | L101  | ESSENTIO DR SL     | 00802526572180 | L210  | PROPONENT MRI SR SL | 00802526578076 | L311  | ACCOLADE MRI DR SL     |
| 00802526558931 | L101  | ESSENTIO DR SL     | 00802526576393 | L210  | PROPONENT MRI SR SL | 00802526609008 | L311  | ACCOLADE MRI DR SL     |
| 00802526571961 | L101  | ESSENTIO DR SL     | 00802526576898 | L210  | PROPONENT MRI SR SL | 00802526611896 | L311  | ACCOLADE MRI DR SL     |
| 00802526571978 | L101  | ESSENTIO DR SL     | 00802526578021 | L210  | PROPONENT MRI SR SL | 00802526559242 | L321  | ACCOLADE DR EL         |
| 00802526576317 | L101  | ESSENTIO DR SL     | 00802526609077 | L210  | PROPONENT MRI SR SL | 00802526559259 | L321  | ACCOLADE DR EL         |
| 00802526576812 | L101  | ESSENTIO DR SL     | 00802526611773 | L210  | PROPONENT MRI SR SL | 00802526572425 | L321  | ACCOLADE DR EL         |
| 00802526593116 | L101  | ESSENTIO DR SL     | 00802526559099 | L211  | PROPONENT MRI DR SL | 00802526572432 | L321  | ACCOLADE DR EL         |
| 00802526611629 | L101  | ESSENTIO DR SL     | 00802526559105 | L211  | PROPONENT MRI DR SL | 00802526576478 | L321  | ACCOLADE DR EL         |
| 00802526558948 | L110  | ESSENTIO MRI SR SL | 00802526572210 | L211  | PROPONENT MRI DR SL | 00802526576973 | L321  | ACCOLADE DR EL         |
| 00802526558955 | L110  | ESSENTIO MRI SR SL | 00802526576409 | L211  | PROPONENT MRI DR SL | 00802526593260 | L321  | ACCOLADE DR EL         |
| 00802526571985 | L110  | ESSENTIO MRI SR SL | 00802526576904 | L211  | PROPONENT MRI DR SL | 00802526611766 | L321  | ACCOLADE DR EL         |
| 00802526572005 | L110  | ESSENTIO MRI SR SL | 00802526578038 | L211  | PROPONENT MRI DR SL | 00802526559266 | L331  | ACCOLADE MRI DR EL     |
| 00802526576324 | L110  | ESSENTIO MRI SR SL | 00802526609022 | L211  | PROPONENT MRI DR SL | 00802526559273 | L331  | ACCOLADE MRI DR EL     |
| 00802526576829 | L110  | ESSENTIO MRI SR SL | 00802526611704 | L211  | PROPONENT MRI DR SL | 00802526572456 | L331  | ACCOLADE MRI DR EL     |
| 00802526609039 | L110  | ESSENTIO MRI SR SL | 00802526559112 | L221  | PROPONENT DR EL     | 00802526572463 | L331  | ACCOLADE MRI DR EL     |
| 00802526611636 | L110  | ESSENTIO MRI SR SL | 00802526559129 | L221  | PROPONENT DR EL     | 00802526572470 | L331  | ACCOLADE MRI DR EL     |
| 00802526558962 | L111  | ESSENTIO MRI DR SL | 00802526572265 | L221  | PROPONENT DR EL     | 00802526576485 | L331  | ACCOLADE MRI DR EL     |
| 00802526558979 | L111  | ESSENTIO MRI DR SL | 00802526576416 | L221  | PROPONENT DR EL     | 00802526576980 | L331  | ACCOLADE MRI DR EL     |
| 00802526572012 | L111  | ESSENTIO MRI DR SL | 00802526576911 | L221  | PROPONENT DR EL     | 00802526578083 | L331  | ACCOLADE MRI DR EL     |
| 00802526572029 | L111  | ESSENTIO MRI DR SL | 00802526578045 | L221  | PROPONENT DR EL     | 00802526592201 | L331  | ACCOLADE MRI DR EL     |
| 00802526572036 | L111  | ESSENTIO MRI DR SL | 00802526593307 | L221  | PROPONENT DR EL     | 00802526609084 | L331  | ACCOLADE MRI DR EL     |
| 00802526576331 | L111  | ESSENTIO MRI DR SL | 00802526611858 | L221  | PROPONENT DR EL     | 00802526611872 | L331  | ACCOLADE MRI DR EL     |
| 00802526576836 | L111  | ESSENTIO MRI DR SL | 00802526559136 | L231  | PROPONENT MRI DR EL | 00802526559327 | S701  | ALTRUA 2 SR SL         |
| 00802526609060 | L111  | ESSENTIO MRI DR SL | 00802526559143 | L231  | PROPONENT MRI DR EL | 00802526559334 | S701  | ALTRUA 2 SR SL         |
| 00802526611612 | L111  | ESSENTIO MRI DR SL | 00802526572272 | L231  | PROPONENT MRI DR EL | 00802526572487 | S701  | ALTRUA 2 SR SL         |
| 00802526558986 | L121  | ESSENTIO DR EL     | 00802526576423 | L231  | PROPONENT MRI DR EL | 00802526576492 | S701  | ALTRUA 2 SR SL         |
| 00802526558993 | L121  | ESSENTIO DR EL     | 00802526576928 | L231  | PROPONENT MRI DR EL | 00802526576997 | S701  | ALTRUA 2 SR SL         |
| 00802526572043 | L121  | ESSENTIO DR EL     | 00802526578052 | L231  | PROPONENT MRI DR EL | 00802526578090 | S701  | ALTRUA 2 SR SL         |
| 00802526576348 | L121  | ESSENTIO DR EL     | 00802526609046 | L231  | PROPONENT MRI DR EL | 00802526593222 | S701  | ALTRUA 2 SR SL         |
| 00802526576843 | L121  | ESSENTIO DR EL     | 00802526611780 | L231  | PROPONENT MRI DR EL | 00802526611841 | S701  | ALTRUA 2 SR SL         |
| 00802526593277 | L121  | ESSENTIO DR EL     | 00802526559150 | L300  | ACCOLADE SR SL      | 00802526559341 | S702  | ALTRUA 2 DR SL         |
| 00802526611650 | L121  | ESSENTIO DR EL     | 00802526559167 | L300  | ACCOLADE SR SL      | 00802526559358 | S702  | ALTRUA 2 DR SL         |
| 00802526559006 | L131  | ESSENTIO MRI DR EL | 00802526572302 | L300  | ACCOLADE SR SL      | 00802526572517 | S702  | ALTRUA 2 DR SL         |
| 00802526559013 | L131  | ESSENTIO MRI DR EL | 00802526576430 | L300  | ACCOLADE SR SL      | 00802526576508 | S702  | ALTRUA 2 DR SL         |
| 00802526572074 | L131  | ESSENTIO MRI DR EL | 00802526576935 | L300  | ACCOLADE SR SL      | 00802526577000 | S702  | ALTRUA 2 DR SL         |
| 00802526572081 | L131  | ESSENTIO MRI DR EL | 00802526593321 | L300  | ACCOLADE SR SL      | 00802526578106 | S702  | ALTRUA 2 DR SL         |
| 00802526576355 | L131  | ESSENTIO MRI DR EL | 00802526611810 | L300  | ACCOLADE SR SL      | 00802526593208 | S702  | ALTRUA 2 DR SL         |
| 00802526576850 | L131  | ESSENTIO MRI DR EL | 00802526559174 | L301  | ACCOLADE DR SL      | 00802526611759 | S702  | ALTRUA 2 DR SL         |
| 00802526609053 | L131  | ESSENTIO MRI DR EL | 00802526559181 | L301  | ACCOLADE DR SL      | 00802526559365 | S722  | ALTRUA 2 DR EL         |
| 00802526611643 | L131  | ESSENTIO MRI DR EL | 00802526572333 | L301  | ACCOLADE DR SL      | 00802526559372 | S722  | ALTRUA 2 DR EL         |
| 00802526559020 | L200  | PROPONENT SR SL    | 00802526572340 | L301  | ACCOLADE DR SL      | 00802526573071 | S722  | ALTRUA 2 DR EL         |
| 00802526559037 | L200  | PROPONENT SR SL    | 00802526572357 | L301  | ACCOLADE DR SL      | 00802526576515 | S722  | ALTRUA 2 DR EL         |
| 00802526572104 | L200  | PROPONENT SR SL    | 00802526576447 | L301  | ACCOLADE DR SL      | 00802526577017 | S722  | ALTRUA 2 DR EL         |
| 00802526576362 | L200  | PROPONENT SR SL    | 00802526576942 | L301  | ACCOLADE DR SL      | 00802526578113 | S722  | ALTRUA 2 DR EL         |
| 00802526576867 | L200  | PROPONENT SR SL    | 00802526593215 | L301  | ACCOLADE DR SL      | 00802526593239 | S722  | ALTRUA 2 DR EL         |
| 00802526578007 | L200  | PROPONENT SR SL    | 00802526611865 | L301  | ACCOLADE DR SL      | 00802526611711 | S722  | ALTRUA 2 DR EL         |
| 00802526593338 | L200  | PROPONENT SR SL    | 00802526559204 | L310  | ACCOLADE MRI SR SL  | 00802526559389 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526611827 | L200  | PROPONENT SR SL    | 00802526559211 | L310  | ACCOLADE MRI SR SL  | 00802526559396 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526559044 | L201  | PROPONENT DR SL    | 00802526572364 | L310  | ACCOLADE MRI SR SL  | 00802526573101 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526559051 | L201  | PROPONENT DR SL    | 00802526572371 | L310  | ACCOLADE MRI SR SL  | 00802526573118 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526572135 | L201  | PROPONENT DR SL    | 00802526572388 | L310  | ACCOLADE MRI SR SL  | 00802526573125 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526576379 | L201  | PROPONENT DR SL    | 00802526576454 | L310  | ACCOLADE MRI SR SL  | 00802526577024 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526576874 | L201  | PROPONENT DR SL    | 00802526576959 | L310  | ACCOLADE MRI SR SL  | 00802526577109 | U125  | VALITUDE CRT-P EL IS-1 |
| 00802526578014 | L201  | PROPONENT DR SL    | 00802526578069 | L310  | ACCOLADE MRI SR SL  | 00802526578793 | U125  | VALITUDE CRT-P EL IS-1 |



Please complete the form & Send it to:  
«Customer\_Service\_Fax\_Number»

«Sold\_to» - «Hospital\_Name» - «City» - «Country\_Name»

---

**Acknowledgement Form – Urgent Field Safety Notice**

**Software available to prevent initiation of Safety Mode for  
ACCOLADE™ Family of Pacemakers and CRT-Ps launch Software**

**97125289E-FA**

---

**By signing this form, I confirm that**

**I have read and understood  
the Boston Scientific Field Safety Notice dated  
20 August 2025 for:**

**Software available to prevent initiation of Safety Mode for  
ACCOLADE™ Family of Pacemakers and CRT-Ps launch Software**

**NAME\*** \_\_\_\_\_ **Title** \_\_\_\_\_

**Telephone** \_\_\_\_\_ **Email** \_\_\_\_\_

**SIGNATURE\*** \_\_\_\_\_ **DATE\*** \_\_\_\_\_  
\* Required field dd/mm/yyyy